



BROCOR
AUCTIONS

DE-FLEET AUCTION
23 JULY 2026 - 10AM



+ LOOSE ASSETS
N12, POTCHEFSTROOM

CATALOGUE

JACO VAN ROOYEN: 082 887 3200

LEWELLEN GREEN: 073 332 4125

WWW.BROCOR.CO.ZA



www.BROCOR.CO.ZA

**REGISTER
ONSITE**

**CLICK
HERE**

PLOT 826 VYFHOEK, POTCHEFSTROOM (N12)
GPS COORDINATES: -26.667954, 27.162588

REGISTER ONLINE

@ ONE OF THESE 2 PLATFORMS

AuctionBids

Auction bids:
auctionbids.co.za

Click here to register



MEERKAT
ONLINE AUCTIONS

Meerkat Online:
www.meerkatonline.co.za

Click here to register



AUCTION RULES

- 1 • You have to be registered to participate on this auction.
By Registering you agree to the terms and conditions.
- 2 • 10% + VAT commission payable on top of your bid price.
- 3 • This auction is not subject to finance you will be held to your bid.
- 4 • Payment should be made within 24 hours.
No item will be removed before payment has been made.
- 5 • If registration papers are applicable to an item the auctioneer will highlight such. Transfer of ownership should take place within 21 days after the item was bought. R 1000 administration fee will be charged for the buyer.
- 6 • VAT is payable on all the items except otherwise mentioned.
- 7 • All the information on the items that are being sold was given to us by the seller and Brocor Auctions will take no responsibility for incorrect information.
- 8 • Make sure of the condition and information before you bid.
All items will be sold voetstoots.
All items will be sold subject to viewing. Viewing must take place within 7 days of the auction. If the item is not in the condition as advertised, Brocor will pay your money back. Should the item not be viewed within 7 days no refunds will be given.
- 9 • You will have until the 30 th of July 2026 to remove the items you bought from the day of the auction. The loading and transportation of the items is the responsibility of the buyer.
Brocor Auctions will however assist where possible.

LOT
1**MAN TGS 27.440**

📅 2011 Model 🚗 HRS / KM
974394

Interior worn/fair condition
Front Bumper Dented / Rusted
Drivers outside mirror no bottom cover - Cable Tied
Danger Triangle Sticker cracked
No Fog light left front
No Headlight Right Front
Chassiss need Repaint / Faded
Wiring needs attention for

HAS PAPERS**VAT TRANSACTION****Location: Potchefstroom**LOT
2**MERCEDES BENZ ECOLINER**

📅 1998 Model 🚗 HRS / KM
534787

Interior fair condition
Bumper Resprayed
Window Washers not connected
Front Bumper at the passenger's stairs - Cracked
Roof Rusted
Rear cab Rusted
Runner
Tyres Average

HAS PAPERS**VAT TRANSACTION****Location: Potchefstroom**LOT
3**MERCEDES BENZ 1417 CRANE TRUCK**

📅 1991 Model 🚗 HRS / KM
640946

Interior worn/fair condition
Front Bumper rusted
No Left / Passenger Mirror
Rear Cab rusted
Rear Lights in good condition
Front Roof has small Dents
Passenger roof at the top has a major bump / Rusted
ENGINE REBUILT
Runner
Tyres Average

HAS PAPERS**VAT TRANSACTION****Location: Potchefstroom**

LOT
4**FREIGHTLINER ARGOSY 60/440**

📅 2006 Model 🚗 HRS / KM
1260033

Interior worn/fair condition
Needs matrass
Cab Conditon Good
Mirrors no Cracks
Cassis overall condition good
Tyres average
NON-Runner

HAS PAPERS**VAT TRANSACTION****Location: Potchefstroom**LOT
5**MERCEDES BENZ POWERLINER 2535**

📅 1995 Model 🚗 HRS / KM
628816

Interior Worn
CAB faded old
Mirrors good Condition
Hydraulic PTO
Rear Cab Paint peeling
Driver Door Cracks
Roof faded rusted
NON-Runner
Enginer turning
One tyre flat and torn

HAS PAPERS**VAT TRANSACTION****Location: Potchefstroom**LOT
6**SCANIA R420**

📅 2010 Model 🚗 HRS / KM
833755

Interior Worn
Roof Scoop - Broken at Bracket Left
Drivers Small Mirror Needs Glass
Mirrors At Passengers Side Good Condition
Tank Faded - Spots
Mudflaps left and Right Cracked - Torn
Air Hoses - open
COC Tank Dented
Right Tank side Scratched
Stick

HAS PAPERS**VAT TRANSACTION****Location: Potchefstroom**

LOT
7**KIA K2700 WORK HORSE**

📅 2017 Model 🚗 HRS / KM
229704

Interior fair/good condition
Windscreen Cracked
Cab Good Condition
DropDown small scratches
Trailer Hook
Driver door Dent
STARTER- MISS FIRE
Tyres Average

HAS PAPERS**VAT TRANSACTION****Location: Potchefstroom**LOT
8**TOYOTA HILUX D-4D**

📅 2007 Model 🚗 HRS / KM
719308

Doors Working Both Sides
Roof Light Working
HandBrake Not working
Seatbelts Working
No Back Tail
No Antenna
Left Headlight Faded
All Lights working
Trailer Hook
Body Good Condition
STARTER: Warning Signs - Petrol Light , T-Belt , Engine Check Lig

HAS PAPERS**VAT TRANSACTION****Location: Potchefstroom**LOT
9**HYUNDAI H100**

📅 2010 Model 🚗 HRS / KM
339803

Interior fair
Windscreen Cracked
Dropsides Working Rubber Torn
Mirrors Good Condition
Runner - mechanically good condition
Engine reconditioned
tyres Average

HAS PAPERS**VAT TRANSACTION****Location: Potchefstroom**

LOT
10

MAN TGM 18.280

2009 Model HRS / KM
762812

Interior Good Condition
Sails Faded
Tail Lift with all components
Clutch replaced
Runner - mechanically good condition
tyres Average

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
11

MISTUBISHI FUSO FE-150

2015 Model HRS / KM
348926

Interior Good condition
Drop Sides Paint Job Needed
Tyres Average
Runner - mechanically good condition

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
12

MAN TGA 26.480

2009 Model HRS / KM
942295

Interior fair/good condition
Driver Door Outside small Rust
CAB Paint Faded
Bumper at Passenger damaged
PTO unit with hydraulic system
12 Astronic 2331 TD Gearbox Overall 2022/10/31
Intercooler 2021/06/23 Replaced
Repair Radiator 2021/06/23
Engine Se

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
13

MAN 27.423

1999 Model HRS / KM
760533

Interior Worn
One Side Shaft Seal Leaks
2x Brake Booster Leaks
Air leaks
Pipes - AZR old
Clutch Slave Cylinder not working
Split valve Leak
5th Wheel Torn
Right Front Headlight Broken
Chassis needs to be repainted
Front Bumper Needs a Repaint
Sid

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
14

CHEVROLET UTILITY SPORT

2012 Model HRS / KM
438610

Interior Good condition
Exterior Good Condition
Sail torn
Runner - mechanically good condition
Tyres Average

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
15

CHEVROLET UTILITY SPORT

2015 Model HRS / KM
325723

Interior Good condition
Exterior Good Condition
Runner - mechanically good condition
Tyres in Good condition

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
16

MAN TGA RIGID

2007 Model HRS / KM
863135

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
17

MAN F2000

2000 Model HRS / KM
356202

NO Engine
NO Gearbox

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
18

TOYOTA ETIOS SEDAN

2018 Model HRS / KM
197824

Interior Good condition
Exterior Good condition
Runner - mechanically good condition

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
19

MERCEDES BENZ S350

2011 Model HRS / KM
343699

Baie goed kondisie
Meganies is hy 100%
Is nog in daaglikse gebruik

HAS PAPERS


NO VAT ON ITEM

Location: Potchefstroom



LOT
20**LAND ROVER DISCOVERY HSE TDV6** 2014 Model  HRS / KM
212979

Engine replaced on 210 000km
One owner
Good condition

HAS PAPERS**NO VAT ON ITEM****Location: Potchefstroom**LOT
21**TRUCK BUMPER****NO PAPERS****VAT TRANSACTION****Location: Potchefstroom**LOT
22**PLATIC PIPING****NO PAPERS****VAT TRANSACTION****Location: Potchefstroom**LOT
23**50LT COMPRESSOR TANK****NO PAPERS****VAT TRANSACTION****Location: Potchefstroom**

LOT
24**2X TRUCK SIDE DIESEL TANKS**

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom

LOT
25**KDE 20SS3 HEAVY DUTY GENERATOR**

Motor Not working

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom

LOT
26**TRUCK MIDDLE PROPSHAFT**

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom

LOT
27**SCRAP METAL**

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
28

49X 210 LITER STEEL DRUMS

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom




LOT
29

20X 210 LITER PLASTIC DRUMS

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
30

19X COC FILLING STATION PUMPS

2 motors dressers wayne 47870 PIC 3
Not working

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom




LOT
31

4X WINDOW FRAMES

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
32

OLD PRESSURE HOSES

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom




LOT
33

9X ALUMINUM GLAS DOORS

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
34

209X WOOD PALLETS

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
35

GENERATOR REEF FLEX ENGIN

Not Working

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
36**HILUX BAKKIE BULLBAR AND ROLLBAR**

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom

LOT
37**OPEN GEARBOX**

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom

LOT
38**DIFF WITH DISCS**

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom

LOT
39**3 LEG STAND FOR ENGINE REMOVAL**

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
40

BRAKE BOOSTERS

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
41

2X LAS PETROL METERS

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
42

STAAL RAKKE

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
43

CHEVAL LIBETTE MAXI 2 HORSEBOX

2022 Model

HAS PAPERS

NO VAT ON ITEM

Location: Potchefstroom



LOT
44

2X WORKSHOP CAR LIFT

Needs to be assembled

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
45

MAHINDRA PIK-UP BAKKIE

2020 Model HRS / KM
157858

Working Condition

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
46

ISUZU PICK-UP BAKKIE

unknown Model HRS / KM
unknown

BAKKIE WAS USED ON A FARM
HAS A TOYOTA 4Y MOTOR
WORKING CONDITION

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
47

TATA NOVUS 5542 TIPPER TRUCK

2006 Model HRS / KM
275 075

LOAD CAPACITY: 10 TON
MANUAL TRANSMISSION
DIESEL FUEL TYPE
WORKING CONDITION
ODOMETER NOT GARUNTEED

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
48

MERCEDES-BENZ ACTROS TIPPER TRUCK

TIPPER CAPACITY: 20m³
TRUCK WAS USED ON A MINING SITE
WORKING CONDITION

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
49

MERCEDES-BENZ 1213 FLAT DECK TRUCK

MANUAL TRANSMISSION
DIESEL FUEL TYPE

NO PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
50

FORD RANGER XLT 3L BAKKIE

2010 Model HRS / KM
279405

WORKING CONDITION

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
51

FORD RANGER XLT 3L BAKKIE

2011 Model HRS / KM
258100

WORKING CONDITION

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
52

BELL 315SJ TURBO 4X4 TLB

 unknown Model  HRS / KM
unknown

4X4 WHEEL DRIVE
BUCKET CAPACITY: 0.77m³
GROSS POWER: 69 KW
FUEL CAPACITY: 155 LITRE
POWERSHIFT TRANSMISSION
MAX. SPEED (FORWARD): 38.4 KM/H
MAX. SPEED (REVERSE): 22.5 KM/H
WORKING CONDITION

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
53

MAN F2000 ENGINE AND GEARBOX

NOT TESTED

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



LOT
54

13 WELDERS

Not Working

HAS PAPERS

VAT TRANSACTION

Location: Potchefstroom



XEROX PRINTER

HAS PAPERS**LOT
55****VAT TRANSACTION****Location: Potchefstroom**

AUCTION



AJ Du Plessis

Cell: 073 091 3878 | Email: aj@brocor.co.za

WWW.BROCOR.CO.ZA

